

## Resurvey of South Boundary of T. 31 S., R. 2 W.

CHAINS

- 18.75 Ravine, course NW
- 25.00 Ridge Point descending NW
- 32.00 Creek, 2 lks. wide, course NW
- 40.24 Set a slate stone 18x12x3 ins. <sup>12 ins.</sup> in the ground for  $\frac{1}{4}$  sec. cor.  
marked  $\frac{1}{4}$  on W face from which
- A Madrone, 9 ins. diam., bears N.65\*E., 30 lks. dist.  
Marked  $\frac{1}{4}$  S 33 B T
- A Madrone, 7 ins. diam., bears N.3\*W., 20 lks. dist.  
Marked  $\frac{1}{4}$  S 33 B T
- 43.00 Ridge bears NW & SE  
Descends NE slope
- 44.73 The old  $\frac{1}{4}$  sec. cor.  
I destroy the cor. and marks on bearing trees
- 45.10 The closing cor. of secs. 4 & 5, T. 32 S., R. 2 W.  
Thence N.89\*47'E.
- 48.50 Ravine, course North
- 49.00 Ravine, course NW  
Descend E slope
- 68.00 High ridge bears NW & SE
- 80.48 The closing cor. of secs. 33 & 34  
Land Mountainous  
Soil, stony, 3rd. rate  
Timber, Fir, Cedar, Madrone  
Undergrowth Hazel, Vinemaple  
Mountainous or heavily timbered land or land covered with  
dense undergrowth and exceptionally difficult to survey  
80.48 chs.

July 9, 1908

Thence I run

N.89\*47'E., on South Boundary sec. 34

Over Mountainous land, heavily timbered and covered with  
dense undergrowth

Descend East slope

3.10 Creek, 3 lks. wide, course North

Ascend West slope

4.32 The old cor. of secs. 33 &amp; 34