

County Surveyor's Record, Douglas County, Oregon

7629
X
27

Resurvey of South Boundary of T;31 S., R. 2 W.

CHAINS	I destroy the cor. and marks on bearing trees
14.50	Ridge bears N & S Descend NE slope
20.50	Ravine, course North Ascend NW slope
39.25	Ridge bears NE & SW Descend E slope
40.16 $\frac{1}{2}$	Set a Granite stone 12x10x8 ins., 8 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N face from which A Fir, 8 ins. diam., bears N.10*E., 71 lks. dist., Marked $\frac{1}{4}$ S 34 B T A Madrone, 10 ins. diam., bears N.75*W., 38 lks. dist., Marked $\frac{1}{4}$ S 34 B T
43.85	The old $\frac{1}{4}$ sec. cor. I destroy the cor. and marks on bearing trees
45.35	The closing cor. of secs. 3 & 4, T. 32 S., R. 2 W. Thence N.89*55'E.
50.50	Creek, 8 lks. wide, course NW Ascend West slope
54.00	Low ridge bears NW & SE Ascend gradual West slope
80.33	The closing cor. of secs. 34 & 35 Land Mountainous Soil, stony, 3rd. rate Timber, Fir, Cedar, Madrone Undergrowth Hazel, Madrone, Vinemaple Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey 80.33 chs. July 10, 1908
	Thence I run N.89*55'E., on South Boundary sec. 35 Over Mountainous land, heavily timbered and covered with dense undergrowth Ascend NW slope
L60	Trail to Rowley Copper Mine bears N & S