

Resurvey of the South Boundary of T. 31 S., R. 2 W.

CHAINS I destroy the cor. and marks on bearing trees

10.25 Creek, 5 lks. wide, course North

Ascend NW slope

30.00 Ridge bears N & S

Along North slope

31.00 Enterswamp

39.00 Leave swamp

40.81 $\frac{1}{2}$ Set a basalt stone 15x8x6 ins., 10 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N face from which

A Fir, 16 ins. diam., bears N.55*E., 54 lks. dist.
Marked $\frac{1}{4}$ S 36 B T

A Fir, 14 ins. diam., bears N.75*W., 25 lks. dist.
Marked $\frac{1}{4}$ S 36 B T

Ascend gradual E. slope

42.15 The old $\frac{1}{4}$ sec. cor.

I destroy the cor. and marks on bearing trees

43.60 The closing cor. of secs. 1 & 2, T. 32 S., R. 2 W.

58.75 Ridge bears NE & SW

Along S slope

81.63 The cor. of T. 31 S., Rs. 1 & 2 W.

Land Mountainous

Soil, stony, 3rd. rate

Timber, Fir, Cedar: Undergrowth, Vinemaple, Hazel, Lilac,
Fir

Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.

81.63 chs.

July 11, 1908

Subdivisions of T. 31 S., R. 2 W.
Same Deputy and Contract

At the cor. of secs. 25, 26, 35 & 36 which is nearly obliterated cor. and bearing trees are deeply overgrown I reestablish the cor. in its original position as follows

A White Oak, 12 ins. diam., for cor. of secs. 25, 26,
35 & 36

I mark