

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R. 2 W.

CHAINS	<p>Land Mountainous</p> <p>Soil, granite and stony, 3rd. rate</p> <p>Timber, Fir, Hemlock, Cedar; undergrowth Hemlock, Vine-Maple, Hazel</p> <p>Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey</p> <p>48.68 chs.</p> <p style="text-align: right;">October 27, 1906</p> <hr/> <p>Thence I run</p> <p>S.0*1'E. bet. secs. 35 &amp; 36</p> <p>Over Mountainous land, heavily timbered and covered with dense undegrowth</p> <p>11.80 Creek, 3 lks. wide, course NE</p> <p>Ascend N slope</p> <p>20.50 Ridge bears NE &amp; SW</p> <p>Descend SE slope</p> <p>31.00 Ridge Point descending NE</p> <p>38.85 Creek, 5 lks. wide, course NE</p> <p>Ascend N slope</p> <p>40.00 Set an ironstone 12x10x6 ins. 8 ins. in the ground for <math>\frac{1}{4}</math> sec. cor. Marked <math>\frac{1}{4}</math> on W face from which</p> <p style="padding-left: 40px;">A Fir, 18 ins. diam., bears N.73*E., 42 lks. dist.</p> <p style="padding-left: 40px;">Marked <math>\frac{1}{4}</math> S 36 B T</p> <p style="padding-left: 40px;">A Fir, 18 ins. diam., bears S.40*W., 42 lks. dist.,</p> <p style="padding-left: 40px;">Marked <math>\frac{1}{4}</math> S 35 B T</p> <p>77.35 Ridge bears NE &amp; SW</p> <p>80.85 Intersect N bdy. of the T. 35.50 chs. N.89*58'E., of the closing cor. of secs. 2 &amp; 3 T. 32 S., R. 2 W.</p> <p>Set a basalt stone 15x10x5 ins. 10 ins. in the ground for closing cor. of secs. 35 &amp; 36 marked CC on N with 1 groove on E and 5 grooves on W face from which</p> <p style="padding-left: 40px;">A Fir, 16 ins. diam., bears N.30*E., 30 lks. dist.,</p> <p style="padding-left: 40px;">Marked T 31 S R 2 W S 36 B T</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears N.45*W., 5 lks. dist.,</p> <p style="padding-left: 40px;">Marked T 31 S R 2 W S 35 B T</p>
--------	---