

County Surveyor's Record, Douglas County, Oregon

7641
49

Subdivisions of T. 51 S., R. 2 W.

CHAINS	<p>Leave Thicket</p>
63.00	<p>Ridge bears NW & SE</p> <p>Descend NE slope</p>
81.30	<p>Intersect E & W line 1.34 chs. E of the cor. of secs. 22, 23, 26 & 27</p> <p>Set a basalt stone 15x8x6 10 ins. in the ground for closing cor. of secs. 26 & 27 marked CC on S with 2 grooves on S and E face from which</p> <p style="padding-left: 40px;">A Fir, 36 ins. diam., bears S.74*E., 26 lks. dist. Marked T 31 S R 2 W S 26 B T</p> <p style="padding-left: 40px;">A Fir, 36 ins. diam., bears S.27*W., 51 lks. dist. Marked T 31 S R 2 W S 27 B T</p> <p>The old cor. of secs. 22, 23, 26 & 27 is nearly obliterated. No trace is found by the post and the NE bearing tree is destroyed by fire, the other deeply overgrown. I reestablish the cor. in its original position as follows for cor. secs. 22 & 23 only</p> <p>Set a basalt stone 24x12x6 ins. 18 ins. in the ground for cor. of secs. 22 & 23 marked with 2 notches on E edge from which</p> <p style="padding-left: 40px;">A Fir, 14 ins. diam., bears N.11*E., 71 lks. dist. Marked T 31 S R 2 W S 23 B T</p> <p style="padding-left: 40px;">A Pine, 36 ins. diam., bears N.62*W., 22 lks. dist. Marked T 31 S R 2 W S 22 B T</p> <p>Old marks referring to secs. 26 & 27 already obliterated</p> <p>Land Mountainous</p> <p>Soil, Clay 2nd. rate</p> <p>Timber, Fir, Pine; undergrowth Hazel, Fir, Oak,</p> <p>Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.</p> <p>81.30 chs.</p> <p style="text-align: right;">October 30, 1906</p>

Thence I run
S.0*2'E., bet. secs. 33 & 34
Over Mountainous land heavily timbered and covered with