

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R 2 W.

CHAINS	Ascend SE slope
43.50	Creek, 2 lks. wide, course S
74.00	Leave heavy timber, bears NE and SW
78.00	Ridge point descending S.30*W. Descend SW slope
79.64	Enter heavy timber bears N & S The cor. of secs. 19, 20, 29 & 30 Land Mountainous Soil, Granite, 3rd. rate Timber, Fir, Hemlock, Cedar; undergrowth, Hemlock, Hazel, Lilac. Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey. 79.64 chs. June 23, 1908
	Thence I run West bet secs. 19 & 30 Over Mountainous land, heavily timbered and covered with dense undergrowth Along S slope
4.50	Creek, 2 lks. wide, course S.10*E. Ascend NE slope
10.50	Creek, 4 lks. wide, course SE
16.50	Creek, 4 lks. wide, course SE
39.75	Ravine, course N.20*E.
40.00	Set a Granite stone 15x8x8 ins. 10 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N face from which A Fir, 36 ins. diam., bears N.62 $\frac{1}{2}$ *W., 29 lks. dist., Marked $\frac{1}{4}$ S 19 B T A Hemlock, 5 ins. diam., bears S.7 $\frac{1}{2}$ *W., 23 lks. dist. Marked $\frac{1}{4}$ S 30 B T
48.93	Intersect West boundary of the T. 4.91 chs. N of the cor. of secs. 19, 24, 25 & 30 which is a granite stone 5x8x6 ins. above ground firmly set marked and witnessed as described by the surveyor general. Set a Granite stone 15x10x6 ins. 10 ins. in the ground