

County Surveyor's Record, Douglas County, Oregon.

7657
65

Subdivisions of T. 31 S., R. 2 W.

CHAINS

10.25 Divide bet. Callahan and Hatchet Creeks bears N & S
Descend W slope

24.50 Head of Ravine, course S.70*W.

26.00 Ridge Point descending S.70*W.

35.35 Hatchet Creek, 8 lks. wide, course N
Ascend E slope

40.00 Set a granite stone 15x10x4 ins. 10 ins. in the ground
for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N face from which
A Fir, 40 ins. diam., bears N.70*W., 38 lks. dist.,
Marked $\frac{1}{4}$ S 18 B T
A Fir, 18 ins. diam., bears S.41 $\frac{1}{2}$ *W., 20 lks. dist.,
Marked $\frac{1}{4}$ S 19 B T

49.40 Intersect W boundary of the T. 3.28 chs. N of the cor. of
secs. 13, 18, 19 & 24 which is a Fir Post 4 ins. sq. 12
ins. above ground marked and witnessed as described by
the surveyor general
No stones obtainable
Set a Cedar Post 3 ft. long 4 ins. sq. 24 ins. in the
ground for closing cor. of secs. 18 & 19 marked
S 18 on N
CC T 31 S R 2 W on E and
S 19 on S face with 3 grooves on N & S faces from
which
A Fir, 24 ins. diam., bears N.70*E., 11 lks.
dist., Marked T 31 S R 2 W S 18 B T
A Fir, 24 ins. diam., bears S.31*E., 20 lks.
dist., Marked T 31 S R 2 W S 19 B T

Land Mountainous
Soil, Granite and stony, 3rd. rate
Timber, Fir, Hemlock, Cedar; Undergrowth, Hemlock,
Madrone, Hazel.
Mountainous or heavily timbered land or land covered
with dense undergrowth and exceptionally difficult
to survey. 49.40 chs.

June 25, 1908