

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R. 2 W.

CHAINS

Land Mountainous

Soil, stony, 3rd. rate

Timber, Fir, Cedar; Undergrowth Madrone, Lilac, Hazel

Mountainous or heavily timbered land or land covered with
dense undergrowth and exceptionally difficult to survey.

40.35 chs.

June 28, 1908

41.75

From the $\frac{1}{4}$ sec. cor. bet. secs. 4 & 5 I run

North on a random line bet. secs. 4 & 5

Intersect North boundary of the T. 1.23 chs. W of the
cor. of secs. 4, 5, 32 & 33

A Fir, 36 ins. diam. for closing cor. of secs. 4 & 5

I Mark

S 4 on E

CC T 31 S R 2 W on S and

S 5 on W side, with 4 notches on E and 2 notches
on W side from whichA Fir, 12 ins. diam., bears S.33*E., 52 lks.
dist., Marked T 31 S R 2 W S 4 B TA Madrone, 20 ins. diam., bears S.1*W., 29
lks. dist., Marked T 31 S R 2 W S 5 B T

The old cor. of secs. 4, 5, 32 & 33 is nearly obliterated

No trace of the post is found

Two bearing trees are standing with marks defaced

I reestablish this cor. in its original position as the
cor. of secs. 32 & 33 T 30 S R 2 W only as follows

No stones obtainable

Set a Fir Post 3 ft. long, 4 ins. sq. 24 ins. in the ground
for cor. of secs. 32 & 33 marked T 30 S S 33 on NE and
R 2 W S 32 on NW face, with 4 notches on E and 2
notches on W edge from whichA Fir, 10 ins. diam., bears N.50*E., 58 lks. dist.
Marked T 30 S R 2 W S 33 B TA Fir, 36 ins. diam., bears N.3*W., 40 lks. dist.,
Marked T 30 S R 2 W S 32 B T