

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R 2 W.

CHAINS

40.00 Set a Granite stone 18x8x8 ins. 12 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N face from which
 A Fir, 30 ins. diam., bears N.67*W., 25 lks. dist.,
 Marked $\frac{1}{4}$ S 6 B T
 A Fir, 36 ins. diam., bears S.70*W., 17 lks. dist.,
 Marked $\frac{1}{4}$ S 7 B T

45.50 Creek, 2 lks. wide, course NE

50.27 Intersect W boundary of the T. 3.26 chs. N of the cor. of secs. 1, 6, 7 & 12 which is an ironstone 4x10x6 ins. above ground firmly set marked and witnessed as described by the surveyor general.

Set and ironstone 14x10x6 ins. 9 $\frac{1}{2}$ ins. in the ground for closing cor. of secs. 6 & 7 marked CC on E with 1 groove on N and 5 grooves on S face from which

A Cedar, 30 ins. diam., bears N.49*E., 74 lks. dist.
 Marked T 31 S R 2 W S 6 B T

A Fir, 24 ins. diam., bears S.69*E., 34 lks. dist.,
 Marked T 31 S R 2 W S 7 B T

Destroy marks on bearing trees at former cor. referring to secs. 6 & 7

Land Mountainous

Soil, Granite, 3rd. rate

Timber, Fir, Cedar; Undergrowth, Hazel, Lilac, Vinemaple Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.

50.27 chs.

July 2, 1908

Thence I run

N.0*4'W., bet. secs. 5 & 6

Over Mountainous land heavily timbered and covered with dense undergrowth

Along E slope

9.00 Creek, 3 lks. wide, course N.60*E.

18.00 Ridge Point descending N.60*E.

19.00 Ravine course E