North Boundary of T. 31 S., R. 2 W.

CHAINS	
0.25	Ridge, bears N. and S.; desc. W. slope.
9.00	Creek, 5 lks. wide, course NE.; asc. SE. slope.
29.50	Ridge point descending S.
31.50	Head of ravine, course S.
34.25	Ridge point descending S.
37.00	Creek, 3 lks. wide, course S. 30°E.
40.00	Set a granite stone, 15 x 12 x 6 ins., 10 ins. in the ground, for ¼ sec. cor., marked: ¼ on N. face; from which, A fir, 6 ins. diam., bears N. 41½°E., 15 lks. dist., marked: ¼ S 31 BT. A fir, 15 ins. diam., bears N. 18°W., 12 lks. dist., marked: ¼ S 31 BT.
47.37	Intersect W. bdy. of T. 31 S., R. 2 W., 10.25 chs. S. of the NE. cor. which is a granite stone, 5 x 10 x 8 ins. above ground, firmly set, marked and witnessed as described by the Surveyor General, No stones available. Set a madrone post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for closing cor. of Tps. 30 and 31 S., R. 2 W., marked: T30S S31 on N., CC R2W on E., and T31S S6 on S. face, with 6 grooves on E. and S. faces; from which, A fir, 24 ins. diam., bears N. 52½°E., 32 lks. dist., marked: T 30 S R 2 W S 31 BT. A madrone, 6 ins. diam., bears S. 52°E., 42 lks. dist., marked: T 31 S R 2 W S 6 BT. Destroy marks on former cor. and bearing trees referring to T. 31 S., R. 2 W. Land; mountainous. Soil; granite, 3rd. rate. Timber; fir, hemlock, cedar, madrone. Undergrowth; hazel, chinquapin, madrone, lilac. Mountainous or heavily timbered land, covered with dense undergrowth and exceptionally difficult to survey. 47.37 chs. July 3, 1908.

General Description

The land traversed by this line lies on the slopes of Hatchet Creek, a small tributary of the South Umpqua River. The slopes are steep and but little of the adjacent land is available for agriculture. The eastern portion is heavily timbered; the west sparsely.

A little gold quartz has been found in the western portion, and some prospecting has been done.

Note: These two pages were copied from records supplied by Regional Forest Office. Copied May 7, 1937, by Ira F.Rankin.