

## County Surveyor's Record, Douglas County, Oregon

## Retracement of Subdivision Lines of T. 31 S., R 2 W.

CHAINS

10.00 Slough, 20 lks. wide, course SE

16.67 Log fence bears N &amp; S

25.00 Log fence bears NE &amp; SW

29.25 Andersons' cabin bears S.90 lks. dist.

40.74 The cor. of secs. 25, 26, 35 &amp; 36

The course of this line is West and the distance is 40.74 chains.

Land Mountainous

Soil, Loam and stony 1st., 2nd and 3rd rate

Timber, Fir, Madrone, Pine, Cedar; Undergrowth, Madrone  
Hazel, Vinemaple.

Mountainous or heavily timbered land or land covered with  
dense undergrowth and exceptionally difficult to survey.  
81.34 chs.

October 29, 1906

From the cor. of secs. 22 & 23 I run

East on S boundary sec. 23

Over Mountainous land heavily timbered and covered with  
dense undergrowth

Ascend NW slope

1.34 The closing cor. of secs. 26 & 27

11.00 Divide bet. Drew and Elk Creek bears N & S

Descend E slope

22.50 Trail bears NW and SE

40.45 The  $\frac{1}{4}$  sec. cor. which is nearly obliterated

No trace found of the Post

One bearing tree is dead and the other deeply overgrown

I reestablish the cor. in its original position as

follows

Set a basalt stone 12x10x6 ins. 8 ins. in the ground for

$\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  on N face from which

A Madrone, 16 ins. diam., bears N.28\*E., 38 lks.

dist., Marked  $\frac{1}{4}$  S 23 B T

A Fir, 16 ins. diam., bears S.32\*E., 38 lks. dist.,