

County Surveyor's Record, Douglas County, Oregon

Retracement of Subdivision Lines of T. 31 S., R 2 W.

CHAINS

Fir, Lilac

Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.

81.04 chs.

October 30, 1906

At the cor. of secs. 23, 24, 25 & 26

Thence I run

South bet. secs. 25 & 26

Over Mountainous land heavily timbered and covered with dense undergrowth

Ascend NE slope

5.85 Trail bears NW & SE

9.00 Rocky spur descending SE

Descend SE slope

25.00 Creek, 4 lks. wide, course NE

Ascend N slope

37.43 Trail bears NW & SE

40.38 The $\frac{1}{4}$ sec. cor. nearly obliterated

One bearing tree standing

The only remaining evidence of the cor.

I reestablish the cor. in its. original position as follows

Set and ironstone 15x12x10 ins. 10 ins. in the ground for

 $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W face from which

A Fir, 10 ins. diam., bears S.86*E., 20 lks. dist.,

. Marked $\frac{1}{4}$ S 25 B T

A Fir, 12 ins. diam., bears S.70*W., 20 lks. dist.,

. Marked $\frac{1}{4}$ S 26 B T

The course of this line is South and the distance is 40.38 chs.

Commencing at the $\frac{1}{4}$ sec. cor. I run

South bet. secs. 25 & 26

7.25 Ridge Point descending E

17.32 Trail bears NE & SW

20.26 Trail bears NW & SE