

County Surveyor's Record, Douglas County, Oregon

1677  
8

Retracement of Subdivisions of T. 31 S., R. 2 W.

CHAINS	
	<p>chains</p> <p>Land Mountainous</p> <p>Soil, Granite, Clay and stony, 2nd. &amp; 3rd. rate</p> <p>Timber, Fir, Pine, Madrone, Cedar, Oak; Undergrowth Hazel, Fir, Oak, Madrone</p> <p>Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.</p> <p>81.37 chs.</p>
	<p>South bet. secs. 21 &amp; 22</p> <p>Over Mountainous land heavily timbered and covered with dense undergrowth</p> <p>Along E slope</p> <p>1.00 Spring, course E.</p> <p>32.50 Creek, 2 lks. wide, course E</p> <p>40.47 The <math>\frac{1}{4}</math> sec. cor. nearly obliterated</p> <p>No trace is found of the post.</p> <p>One bearing tree has fallen and the other is deeply overgrown</p> <p>I reestablish the cor. in its. original position as follows</p> <p>Set a basalt stone 15x12x6 ins. 10 ins. in the ground for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> on W face from which</p> <p style="padding-left: 40px;">A Fir, 10 ins. diam., bears N.30*E., 14 lks. dist., Marked <math>\frac{1}{4}</math> S 22 B T</p> <p style="padding-left: 40px;">A Fir, 10 ins. diam., bears N.45*W., 9 lks. dist., Marked <math>\frac{1}{4}</math> S 21 B T</p> <p>The course of this line is South and the distance is 40.47 chs.</p> <p>Commencing at the <math>\frac{1}{4}</math> sec. cor. I run</p> <p>South bet. secs. 21 &amp; 22</p> <p>4.50 Creek, 1 lk. wide, course S.80*E.</p> <p>8.50 Leave heavy timber and dense undergrowth bears NW &amp; SE</p> <p>Thence along open rocky slope</p> <p>40.60 The cor. of secs. 21 &amp; 22</p> <p>The course of this line is South and the distance is 40.60</p>