

County Surveyor's Record, Douglas County, Oregon

Retracement of Subdivisions of T. 31 S., R. 2 W.

CHAINS

notches on S edge from which

A Black Oak, 30 ins. diam., bears N.47*E., 92 lks. dist., Marked T 31 S R 2 W S 4 B T

A Yellow Pine, 40 ins. diam., bears S.72*E., 221 lks. dist., Marked T 31 S R 2 W S 9 B T

Thence I run

South on W boundary sec. 9

Over Mountainous land, heavily timbered and covered with dense undergrowth

Descend SE slope

2.00 Leave heavy timber and dense undergrowth bears E & W.

Thence across rocky opening

19.00 Head of ravine, course E

40.53 The $\frac{1}{4}$ sec. cor. partially obliterated bears E. 17 lks. dist.

The post is not found but there are remains of a mound of stone in which it was evidently set

The bearing trees are deeply overgrown

I reestablish the cor. in its original position as follows

Point for $\frac{1}{4}$ sec. cor. falls on the end of a serpentine boulder 30x18x15 ins. above ground on which I

Cut a (x) cross at exact cor. point, $\frac{1}{4}$ on W side from which

A Pine, 20 ins. diam., bears S.60*E., 26 lks. dist. Marked $\frac{1}{4}$ S 9 B T

A Cedar, 30 ins. diam., bears S.40*W., 82 lks. dist. Marked $\frac{1}{4}$ S 8 B T

The course of this line is S.0*15'E., and the distance is 40.25 chs.

Land Mountainous

Soil, Clay and stony, 2nd. & 3rd. rate

Timber, Oak, Pine, Cedar; Undergrowth, Hazel, Oak.

Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey. 40.25 chs.

I commence at the cor. of secs. 9, 10, 15 & 16 which is nearly obliterated.