

County Surveyor's Record, Douglas County, Oregon

Retracement of Subdivisions of T. 31 S., R. 2 W.

CHAINS

40.50 Enter heavy timber and dense undergrowth bears E & W

41.40 Intersect North Boundary of the Township, 80 lks. W of the cor. of secs. 3, 4, 33 & 34 which is partially obliterated, one bearing tree gone, the other bearing trees and cor. deeply overgrown.

I reestablish the cor. in its original position as follows

The original cor.

A Cedar, 15 ins. diam., for cor. of secs. 3, 4, 33 & 34 I remark T 30 S S 34 on NE; R 2 W S 3 on SE; T 31 S S 4 on SW and S 33 on NW side with 3 notches on E and W sides, from which

A Fir, 10 ins. diam., bears N.62°E., 83 lks. dist., Marked T 30 S R 2 W S 34 B T

A Fir, 18 ins. diam., bears S.20°E., 12 lks. dist., Marked T 31 S R 2 W S 3 B T

A Fir, 18 ins. diam., bears S.70°W., 13 lks. dist., Marked T 31 S R 2 W S 4 B T

A Fir, 40 ins. diam., bears N.70°W., 17 lks. dist., Marked T 30 S R 2 W S 33 B T

The course of this line is N.1°35'E., and the distance is 41.40 chs.

Land Mountainous

Soil, Clay and stony, 2nd. & 3rd. rate

Timber, Oak, Fir

Undergrowth, Hazel

Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.

81.85 chs.

June 30, 1908