

Subdivisions of T. 31 S., R. 3 W.

| | |
|--------|--|
| CHAINS | <p>79.54 To a point, 40 lks. N of the cor. to secs. 2, 3, 34 and 35, which is a post, greatly decayed, with marks nearly obliterated, I find the 4 witness trees. At cor. point, set a stone, 12x12x6 ins. 8 ins. in the ground, for cor. to secs. 2, 3, 34 and 35, marked with 2 notches on E and 4 notches on W edges; from which</p> <p style="padding-left: 40px;">A fir, (hemlock) 12 ins. diam., (14 ins. now) bears N.38°E., 19 lks. dist., marked T 31 S R 3 W S 35 B T.</p> <p style="padding-left: 40px;">An alder, 4 ins. diam., bears S.60°E., 34 lks. dist., marked T 32 S R 3 W S 2 B T.</p> <p style="padding-left: 40px;">An alder, 14 ins. diam., bears S.58°W., 47 lks. dist., marked T 32 S R 3 W S 3 B T.</p> <p>This tree is dead. In its stead, I mark</p> <p style="padding-left: 40px;">A fir, 14 ins. diam., which bears S.31°W., 22 lks. dist., T 32 S R 3 W S 3 B T.</p> <p style="padding-left: 40px;">An alder, 24 ins. diam., bears N.70°W., 19 lks. dist., marked T 31 S R 3 W S 34 B T.</p> <p>The course of this line is N.89°43'E.</p> <p>Land, mountainous. 79.54 chs.</p> <p>Soil, 3d rate.</p> <p>Heavily timbered with fir, laurel, hemlock, cedar and maple. W 65.00 chs.</p> <p>Dense undergrowth of vine maple, laurel, hazel, hemlock, cedar and fir. 79.54 chs.</p> |
| 2.91 | <p>From the cor. to secs. 2, 3, 34 and 35 on S bdy. of the tp. I run</p> <p>N.0°2'W., bet. secs. 34 and 35.</p> <p style="text-align: right;">Va. 19½°E.</p> <p>Ascend.</p> <p>A fir, 36 ins. diam., on line marked with 2 notches on N and S sides.</p> |