

Subdivision of T. 31 S., R. 4 W.

CHAINS		
5.00	Top of ridge, course S begin descent.	+100
40.08	Set $\frac{1}{4}$ sec. post, from which A fir, 8 ins. diam., bears N.62*E., 15 lks. dist. A fir, 8 ins. diam., bears S.25*W., 6 lks. dist.	-100
45.00	Top of ridge, course SW.	
60.00	Foot of ridge.	-600
60.50	A creek, 3 lks. wide, course SW.	-600
76.00	Top of ridge, course SW.	-440
80.16	To the cor. to secs. 21, 22, 27 and 28 Land, very broken, 3d rate. Timber, 2d rate, fir, cedar, laurel and yew. Underbrush, same.	-400
October 12, 1871.		
North, bet. secs. 32 and 33.		
Va.20*E.		
5.00	Top of spur, course SE. (along E slope of mountain.)	+300
30.00	Top of spur, course E; begin descent.	+300
40.00	Set $\frac{1}{4}$ sec. post, from which A fir, 12 ins. diam., bears N.30*E., 21 lks. dist. A fir, 10 ins. diam., bears S.40*W., 8 lks. dist.	-200
58.00	A creek, 3 lks. wide, course NE.	-500
64.25	A creek, 2 lks. wide, course E.	-500
76.00	Top of ridge, course E.	-100
80.00	Set post, cor. to secs. 28, 29, 32 and 33, from which A fir, 14 ins. diam., bears N.15*E., 34 lks. dist. A fir, 20 ins. diam., bears S.50*E., 35 lks. dist. A fir, 16 ins. diam., bears S.50*W., 21 lks. dist. A fir, 16 ins. diam., bears N.42*W., 8 lks. dist. Land, mountainous, 3d rate. Timber, poor 3d rate, brushy and broken.	
East, on random line, bet. secs. 28 and 33.		
Va.20*E.		