

County Surveyor's Record, Douglas County, Oregon

X ✓

Subdivision of T. 31 S., R. 4 W.

CHAINS

At cor. point

I set a stone, 16x8x6 ins. 12 ins. in the ground, for cor. to secs. 1 and 12, marked with 1 notch on N and 5 notches on S edges; from which

A laurel, 14 ins. diam., bears N.28*E., 24 lks. dist., marked T 31 S R 4 W S 6 B T.

A laurel, 16 ins. diam., bears S.67*E., 29 lks. dist., marked T 31 S R 4 W S 7 B T.

The bearing trees in secs. 1 and 12 are destroyed by fire. I mark 2 new trees as follows

A fir, 32 ins. diam., bears S.13*W., 109 1/2 lks. dist., marked T 31 S R 5 W S 12 B T.

A laurel, 12 ins. diam., bears N.13*W., 35-3/4 lks. dist., marked T 31 S R 5 W S 1 B T.

As this is a cor. to secs. 1 and 12, I destroy the marks on the 2 laurels E of this cor. in T 31 S., R. 4 W.

I measure N to temp. post, 10.25 chs. As this closing is not within the prescribed limit, I begin at the cor. to secs. 1 and 12.

Thence I run

South, on a blank line, bet. secs. 7 and 12.

Va.18-3/4*E.

Descend steeply.

18.45 A stream, 5 lks. wide, course W; ascend. -700 +700

37.25 Summit of ridge, course E and W; descend. -800

40.00 Set temp. post. The 1/4 sec. post is gone. I find 1 bearing tree.

At cor. point

Set a stone, 15x12x10 ins. 10 ins. in the ground, for 1/4 sec. cor. marked 1/4 on W face; from which

A live oak, 10 ins. diam., (12 ins. now) bears S.68*E., 6 lks. dist., marked 1/4 S B T.

The laurel witness tree in sec. 12 is burnt. I mark