

Exterior Lines, Tp. 31 S., R 5W., W. M.

CHAINS

	A Laurel, 6 ins. diam., bears S.76°E., 10 lks. dist.	
	A Live Oak, 3 ins. diam., bears N.59°W., 19 lks.	
41.75	A Branch 1 lk. wide c SE.	-50
59.00	Summit of line on ridge, c E. & W.	+350
64.50	Begin descent	Level
77.15	A Fir, 20 ins. diam.	-280
80.00	Set a post, cor. to secs. 19, 24, 25, & 30, from which	-80
	A Hemlock, 14 ins. diam., bears S.67°W., 32 lks.	
	A Fir, 40 ins. diam., bears N.63°E., 35 lks. dist.	
	A Fir, 36 ins. diam., bears N.62°W., 71 lks. dist.	
	A Fir, 30 ins. diam., bears S.68°E., 50 lks. dist.	
	Rough Mountains, unfit for settlement. Description same as last mile. Timber partly dead.	
	August 15, 1855	

Va. 18°30'E.

	South, on West boundary of sec. 30	
1.45	A Hemlock, 20 ins. diam	-30
1.75	A Branch, 10 lks. wide c E.	Level
13.00	Summit on line of E. Slope	+120
20.50	A Ravine, c E. & W.	-80
24.00	Summit on line of E. Slope	+200
39.80	A Branch, 5 lks. wide. C NE. and begin ascent on NW. Slope of high ridge	-150
40.00	Set $\frac{1}{2}$ sec. post, from which	+10
	A Vine Maple, 6 ins. diam., bears N.54°W., 10 lks.	
	A Vine Maple, 6 ins. diam., bears S.89°E., 4 lks.	
51.00	Summit on line of W. Slope of ridge.	+300
57.75	A Branch, 2 lks. wide., c NW.	-60
59.50	A Fir, 48 ins. diam.	+30
80.00	Set post Cor. to secs. 25, 30, 31, & 36, from which	
	A Fir, 20 ins. diam., bears N.38°W., 16 lks. dist.	
	A Fir, 36 ins. diam., bears S.33°W., 26 lks. dist.	
	A Fir, 20 ins. diam., bears S.68°E., 95 lks. dist.	
	A Yew, 14 ins. diam., bears N.31°E., 64 lks. dist.	