

County Surveyor's Record, Douglas County, Oregon

South Bdy. of T. 31 S. R. 5W.

CHAINS

78.00 Summit of Mt. ridge c SE. & NW. +1200

80.00 Set post cor. to secs. 3, 4, 33, & 34, from which

A Fir, 6 ins. diam., bears S.43*E., 20 lks. dist.

A Fir, 5 ins. diam., bears N.50*E., 31 lks. dist.

A Fir, 6 ins. diam., bears S.71*W., 14 lks. dist.

A Fir, 9 ins. diam., bears N.52*W., 15 lks. dist.

Line runs over high Mt., densely covered with Fir,
Hemlock & Laurel timber, under-growth, Fir, Hazel,
Salal, Manceneta & Red Whortleberry.

Soil, third rate, filled with small angular stone.

Unfit for settlement.

S.89*30*W., on South boundary of sec. 33

Descend SW. slope to head of deep ravine.

40.00 Set $\frac{1}{4}$ sec. post, from which (Va. 18*45'E) -350

A Laurel, 6 ins. diam., bears S.55*E., 46 lks. dist.

A Live Oak, 4 ins. diam., bears N.49*E., 7 lks. dist.

55.00 Mt. peak, 5 chs. S. +800

58.00 Sharp rocky ravine running N. from Mt. side. Walls
nearly perpendicular.76.00 Summit of ridge, c N.85*W., Last 21 chs., along base of
perpendicular ledge about 5 chs., N. of summit of Mt. +100

80.00 Set post cor. to Secs. 4, 5, 32, & 33, from which

A Fir, 12 ins. diam., bears S.39*W., 98 lks. dist.

A Fir, 9 ins. diam., bears N.31*W., 13 lks. dist.

A Fir, 8 ins. diam., bears S.53*30'E., 86. lks. dist.

No tree accessible NE.

High Mt. ridges and deep ravines, very rough

Timber, Fir, Laurel & Live Oak, very thick.

Under growth, Manceneta, Live Oak, Salal & Chinesel.

Soil, Clay, loam filled with stone.

Unfit for settlement.

Va. 18*50'E.

S.89*30*W, on South Boundary of sec. 32

24.00 Enter ravine and run down it