

General Description of S. boundary, T. 31 S., R. 5 W.

CHAINS

This line runs entirely in the canyon mts. crossing the Jacksonville road in the canyon about 2 miles N. of the S. entrance and near the divide of waters in the canyon. The country is uniformly high Mr. ridges and deep ravines, heavily timbered with fir, hemlock, laurel, live oak and chinquapin, with dense undergrowth of fir, laurel, hazel, salal, and live oak. The soil is generally poor on many of the slopes, filled with fine stone and coarse sand, resembling decayed granite. Some slate shale appears on the surface. The country is totally unfit for settlement along the line, being inaccessible for the purpose of agriculture.

Subdivisions of T. 31 S., R. 5 W.,  
As surveyed by W. P. Wright, Deputy Surveyor,  
Under contract No; 281, dated May 16, 1878.

Survey commenced, June 26, 1870.

Begin at the post cor. to secs. 7, 18, 12 and 13.

Township 31, Rs. 5 and 6, W. of Willamette Meridian.

East on true line between secs. 7 and 18. Va. 20\*E.

descend hill slopes E.

30.00 Cross Mitchell Creek, 2 lks. wide, flows N.10\*W., to base steep hill, slopes N.50\*W.

40.00 Set post 4x4 ins. diam., 4 ft. long, 18 ins. in ground, on hill side facing E. Very steep for 1/2 sec. cor., from which

A fir, 30 ins. diam., bears N.38\*E., 15 lks. dist.

A fir, 20 ins. diam., bears N.84\*W., 60 lks. dist.

Raise a very steep hill.

79.00 Top of hill in dense mass of laurel, not over 3 ft. high.

80.00 Set post 5x5 ins. diam., 4 ft. long in mound of rock for cor. to sec. 7, 8, 17 and 18. No witness trees, nothing suitable to mark. This post is on the side of a Mt., sloping S.