

## Subdivisions of T. 31 S., R. 5 W.

CHAINS  
58.50

Cross Branch, 2 lks. wide, flows N.60°E.

76.50

The witness post.

Land, mountainous.

Soil, good, second rate.

Timber, good, fir and cedar.

Commence at Witness post on line bet. secs. 4 and 5,  
900 chs. North of cor. to secs. 4, 5, 8 and 9, thence  
East 10.00 along very bluff hill, South 2.50 to steep  
rock, East 307, South 394, East 1000, South 3.54 to  
line between secs. 4 and 9.

23.07

East of cor. to secs. 4, 5, 8 and 9, set post 4x5 ins. by  
3 $\frac{3}{4}$  ft. long in mound of rock for witness cor., from  
which

A dead fir, 40 ins. diam., bears N.3°W., 138 lks.

A green fir, 10 ins. diam., bears N.50°W., 110 lks.

down hill slopes SE.

40.00

Set post 2x4 ins. by 4 ft. long in mound of rock for  $\frac{1}{4}$   
sec. cor., from which

A fir, 21 ins. diam., bears N.39°E., 30 lks. dist.

A fir, 30 ins. diam., bears N.65°W., 21 lks. dist.

ascend hill.

80.00

Set post 5x5 ins. by 4 $\frac{1}{2}$  ft. long in mound of rock on top  
of ridge to secs. 3, 4, 9 and 10.

No witness trees. This post is in an open place.

Land, rough, mountainous.

Timber, mostly down.

Undergrowth, gooseberries, briars and chaperilla.