

Subdivisions of T. 31 S., R. 5 W.

CHAINS

3 notches on the South and 2 notches on East angles of same for the cor. to secs. 14, 15, 22, & 23, from which,

A Laurel, 4 ins. diam., bears N.5*E., 20 lks.

Marked T 31 S R 5 W S 14 B T.

A Laurel, 5 ins. diam., bears S.65*E., 24 lks.

Marked T 31 S R 5 W S 23 B T.

A Fir, 6 ins. diam., bears S.50*W., 35 lks. dis.

Marked T 31 S R 5 W S 22 B T.

A Live Oak, 6 ins. diam., bears N.25*W., 50 lks.

Marked T 31 S R 5 W S 15 B T.

Land, mountainous and broken

Soil, rocky, fourth rate.

Timber, dense forest of Fir, Cedar and Laurel

Thick undergrowth of Fir, Cedar, & Laurel with Live Oak and Hazel.

Va. 19*E.

East on a Random Line between sections 14 & 23.

25.75 Top of ridge, c NE. Descent

40.00 Set temp. $\frac{1}{4}$ sec. cor.

52.20 A Creek, 2 lks. wide, c NE. Steep ascent.

61.00 Top of spur, c NE. Descent.

80.66 Intersect N & S line, 49 lks. South of Cor. to secs. 13, 14, 23, & 24.

Thence, I run

S.89*39' West on a true line between sections 14 and 23 with same variations.

40.33 Set a Basalt stone, 15x10x8 ins., 10 ins. in ground, marked $\frac{1}{4}$ on North face for the $\frac{1}{4}$ sec. cor, from which

A Fir, 12 ins. diam., bears N.22*W., 13 lks.

Marked $\frac{1}{4}$ S B T.