

Subdivisions of T. 31 S., R. 5 W.:

CHAINS

A Fir, 12 ins. diam., bears N.12*E., 64 lks. dis.
Marked T 30 S R 5 W S 35 B T.

A Fir, 10 ins. diam., bears S.54*E., 72 lks.
Marked T 31 S R 5 W S 2 B T.

A Live Oak, 10 ins. diam., bears S.28*W., 9 lks.
Marked T 31 S R 5 W S 3 B T.

A Fir, 15 ins. diam., bears N.26*W., 14 lks.
Marked T 30 S R 5 W S 34 B T.

Thence, I run

S.1*15*W on a true line between Secs. 2 & 33 with same
variation.

41.40 Set a Laurel post, 3 feet long, 3 ins. diam., 18 ins.
in ground, marked $\frac{1}{4}$ S on West face for the $\frac{1}{4}$ sec.
cor., from which

A Laurel, 14 ins. diam., bears S.65*E., 30 lks.
Marked $\frac{1}{4}$ S B T.

A Laurel, 17 ins. diam., bears N.35*W., 5 lks.
Marked $\frac{1}{4}$ S B T.

81.40 To the corner to secs. 2, 3, 10 & 11.

Land, mountainous and broken.

Soil, rock, third and fourth rates.

Timbers, dense growth of Fir, Laurel, Cedar, Yew, and
Live Oak.

Undergrowth, same kind of woods.

From the corner to sections 3, 4, 33 & 34 on the S.
boundary of the Township, which is a post 4 ins.
square, marked

T 31 S R 5 W S 34 on NE.

T 32 S S 3 on SE.

S 4 on SW. and

S 33 on N.W. faces, with 3 notches on E. & W.
edges, from which