

## County Surveyor's Record, Douglas County, Oregon

West Boundary of  
Township 31 S., Range 6 W.

CHAINS	Surface mostly sloping to the SE. on Mountain side, unfit for settlement. Timber, Pine, Fir, and Laurel, with scattering undergrowth. Soil, 2nd rate for mts.	
	Va. 18°45'E.	
	South, on the W. bdy. of sec. 31	
17.50	Over NW. point of ridge. Enter narrow bottom.	-250
35.00	Branch, 10 lks. wide, course, N.N.W.	level
45.50	Leave bottom, Commence NE. slope.	level
40.00	Set $\frac{1}{4}$ sec. post, from which A Fir, 4 ins. dia., bears S.26°W., 7 lks. dis. A Fir, 12 ins. dia., bears N.49°E., 14 lks. dis.	
70.00	Summit on line of East slope.	+200
75.00	Ravine, course NE.	-100
78.50	Ridge on NE. slope of Mt., course NE.	+100
80.00	Set post cor. to secs. 31 and <sup>36</sup> <del>32</del> S. R. 6 and 7 W. on steep NE. slope, from which A Fir, 10 ins. dia., bears S.64°E., 58 lks. dis. Laurel, 6 ins. dia., bears S.25°W., 53 lks. dis. Laurel, 8 ins. dia., bears N.37°W., 98 lks. dis. Laurel, 12 ins. dia., bears N.78°E., 70 lks. dis.	-20
	Line runs on NE. slope of high ridge and in creek bottom. Rough mountains unfit for settlement. Timber, principally Fir, with thick undergrowth.	
	South Boundary of Township 31 S., Range 6 W. Same Deputy and Contract	
	West, on random on the South bdy. of Tp., No. 31 South of Range No. 6 West, Set temporary mile and half mile posts, and at 6 miles and 3 chains, intersect the East Boundary 2.80 chains North of post at Tp. corner; therefore the correction will be $46\frac{2}{3}$ links south per mile and 3 chs. east. and the true course, N.89°40'W.	