

County Surveyor's Record, Douglas County, Oregon

South Boundary of Township 31 S., R. 6 W.

CHAINS		
	Land, high broken mountainous, unfit for settlement. Heavily timbered with Fir, Laurel and very dense undergrowth of Laurel, Chinquapin, Salal etc. Surface, stony with but little soil.	
	Var. 19°15'E.	
	N.89°40'W. on the South Bdy. of Sec. 34.	
7.00	Pack trail on ridge, course N. & S.	+150
27.25	Spring Branch, 2 lks. wide, course N.20°W.	-700
40.00	Set $\frac{1}{4}$ sec. post on N. slop of Mt, from which	+600
	A Fir, 30 ins. dia., bears S.48°W., 34 lks. dis.	
	A Fir, 30 ins. dia., bears N.44°W., 25 lks. dis.	
52.00	Spring Branch, 1 lk. wide, course North.	-150
60.50	Top of spur from mountain, course North.	+350
80.00	Set post cor. to secs. 3, 4, 33 and 34, from which	-150
	A Fir, 40 ins. dia., bears N.72°E., 72 lks. dis.	
	A Fir, 36 ins. dia., bears S.25°E., 62 lks. dis.	
	A Fir, 30 ins. dia., bears S.4°W., 76 lks. dis.	
	A Fir, 34 ins. dia., bears N.59°W., 73 lks. dis.	
	Line runs on North slope of mountain. Unfit for settlement.	
	Timber, principally fir with dense undergrowth of Laurel, Live Oak, and Salal. Stony with but little soil.	
	Va. 18°30'E.	
	N.89°40'W., on the South bdy. of sec. 33.	
4.00	Summit on N. slope.	+80
28.00	Dry ravine, course North.	-300
37.50	Summit on N. slope.	+350
40.00	Set $\frac{1}{4}$ sec. post on N. slope of Mt. from which	-70
	A Fir, 8 ins. dia., bears N.60°E., 47 lks. dis.	
	A Fir, 12 ins. dia., bears S.55°W., 5 lks. dis.	
60.00	Dry Ravine, course, north.	-200