

South Bdy. of Township 31 S., R. 6 W.

CHAINS		
68.50	Summit on N. slope of Mt.	+250
80.00	Set post cor. to secs. 4, 5, 32 and 33, from which A Chincapin, 6 ins. dia., bears N.35*W., 66 lks. dis. A Chincapin, 3 ins. dia., bears S.65*E., 61 lks. dis. A Laurel, 5 ins. dia., bears N.47*E., 32 lks. dis. A Fir, 18 ins. dia., bears S.34*W., 33 lks. dis. Line on N. slope of mountain, unfit for settlement. Timber, Fir, Live Oak, Laurel and Chincapin, undergrowth of same. But little soil.	-300
13.25	N.89*40*W., on the South bdy. of sec. 32. Va.20*30'E. Spring branch, 1 lk. wide, course North	-150
21.00	Summit on N. slope of Mt.	+200
37.00	Spring Branch, 3 lks. wide, course North.	-300
40.00	Set post on North slope of Mt, from which A Fir, 16 ins. dia., bears N.11*E., 42 lks. dis. A Fir, 5 ins. dia., bears S.42*W., 35 lks. dis.	+175
72.00	Top of ridge from mountain, course NW.	+500
80.00	Set post cor. to secs. 5, 6, 31 and 32, from which A Fir, 8 ins. dia., bears N.17*W., 88 lks. dis. A Fir, 6 ins. dia., bears N.17*E., 86 lks. dis. Laurel, 3 ins. dia., bears S.47*W., 21 lks. dis. (no trees near SE.) Line continues on N. slope of main mountain. Land, rough and rocky, unfit for settlement. Timber, and Undergrowth same as last mile. Very little soil or vegetation.	-75
22.00	N.89*40*W., on the South Bdy. of Sec. 31. Va.19*00'E. Spring Branch, course SW.	-500
37.50	Top of ridge on South slope.	+ 100