

Resurvey of
West Boundary of T. 31 S., R. 6 W., as surveyed by
William H. Byars, Deputy Surveyor, under Contract
No. 448, dated June 13, 1882.

CHAINS

The resurvey of the West Exterior Boundary of Township
31, S., R. 6 W., W. M.

In the subdivision of this township, I was unable to
discover the old corner to Secs. 25, 30, 31 and 36, I
therefore begin at the established corner to Tps.
31 and 32 S., Ranges 6 and 7 West, viz.

A post firmly set in the ground, from which

- A fir, 10 ins. dia., bears S.64*E., 58 lks. dis.
- A Laurel, 6 ins. dia., bears S.35*W., 53 lks. dis.
- A Laurel, 8 ins. dia., bears N.37*W., 98 lks. dis.
- A Laurel, 12 ins. dia., bears N.78*E., 70 lks. dis.

Thence I run

North, bet. secs. 31 and 36.

Va.18*E.

12.50 Descend, N.W. slope.

40.00 Unable to find old corner or traces thereof, therefore.

Set a fir post, 40 ins. long, 3 ins. sq., 20 ins. in the
ground, mkd. $\frac{1}{4}$ S on W. side for the $\frac{1}{4}$ sec. cor.
from which

- A Fir, 16 ins. dia., bears N.58*E., 30 lks. dis.
mkd. $\frac{1}{4}$ S BT.
- A Fir, 20 ins. dia., bears N.34*W., 23 lks. dis.
mkd. $\frac{1}{4}$ S B T.

46.50 A Creek, 12 lks. wide, course N.20*W.

80.00 Set a Laurel post, 4 ft. long, 4 ins. sq., 24 ins. in
the ground mkd. T 31 S R 6 W S 30 on NE., face S.31 on E.
face, S. 36 on the SW. face and R 7 W S 25 on NW. face,
also one notch on S. and five notches on the north
angles of the same for the corner to Secs. 25, 30, 31 and 36
from which