

Resurvey of West Boundary of T. 31 S., R. 6 W.,

CHAINS

The corner to secs. 19, 24, 25 and 30, from which
 A Laurel, 6 ins. dia., bears N.20*E., 15 lks. dis.
 mkd. T 31 S R 6 W S 19 B T.
 A Laurel, 6 ins. dia., bears S.65*E., 16 lks. dis.
 mkd. T 31 S R 6 W S 30 B T.
 A Fir, 6 ins. dia., bears S.14*W., 8 lks. dis.
 mkd. T 31 S R 7 W S 25 B T.
 A Laurel, 12 ins. dia., bears N.35*W., 21 lks. dis.
 mkd. T 31 S R 7 W S 24 B T.

Old corner probably destroyed by fires.

Land, mountainous.

Soil; 2nd and 3rd rate.

Timber, Fir, Pine, Laurel and Cedar.

Thick undergrowth of Fir, Laurel, Pine and Cedar.

Va. 18*30'E.

North, between secs. 19 and 24.

Along E. slope of mountain spur.

- 40.00 Set a cedar post, 40 ins. long, 4 ins. sq., 20 ins. in the ground, mkd. $\frac{1}{4}$ S on W. side for the $\frac{1}{4}$ sec. cor., from which
 A Laurel, 16 ins. dia., bears N.10*E., 26 lks. dis.
 mkd. $\frac{1}{4}$ S B T.
 A Chinquapin, 12 ins. dia., bears N.25*W., 22 lks. dis.
 mkd. $\frac{1}{4}$ S B T.
- 58.15 A creek, 3 lks. wide, course SE. Begin ascent.
- 80.00 Set a Fir post, 4 ft. long, 4 ins. sq., 22 ins. in the ground, mkd. T 31 S R 6 W S 18 on NE. face; S 19 on SE. face; S 24 on SW. face; R 7 W S 13 on NW. face; also three notches on South and North angles of the same for the cor. to secs. 13, 18, 19 and 24, from which
 A Cedar, 16 ins. dia., bears N.22*E., 62 lks. dis.
 mkd. T 31 S R 6 W S 18 B T.
 A Fir, 8 ins. dia., bears S. 62*E., 30 lks. dis.
 mkd. T 31 S R 6 W S 19 B T.