

County Surveyor's Record, Douglas County, Oregon

Resurvey of West Boundary of T. 31 S., R. 6 W.

CHAINS

A Fir, 8 ins. dia., bears S.54*E., 122 lks. dis.
mkd. T 31 S R 6 W S 7 B T.

A Pine, 5 ins. dia., bears S.12*W., 25 lks. dis.
mkd. T 31 S R 7 W S 12 B T.

A Fir, 20 ins. dia., bears N.65*W., 12 lks. dis.
mkd. T 31 S R 7 W S 1 B T.

Old cor. North 2.15 chs. Destroyed same.

Land, mountainous.

Soil; rocky, 3rd rate.

Timbers, good, Fir, Pine, Laurel and Cedar.

Thick undergrowth of Fir, Pine, Laurel and Cedar.

Va. 19*30'E.

North, bet. secs. 1 and 6.

Descend NE. slope of mountain.

40.00 Set a stone 16x14x12, 10 ins. in the ground, mkd. $\frac{1}{4}$ on
W. side for the $\frac{1}{4}$ sec. cor., from which

A Laurel, 8 ins. dia., bears N.78*E., 72 lks. dis.
mkd. $\frac{1}{4}$ S B T.

A Laurel, 5 ins. dia., bears S.50*W., 100 lks. dis.
mkd. $\frac{1}{4}$ S B T.

Old cor. 2.10 chs. north. Destroyed same.

Broken ridges and rough descent.

81.90 Cor. to Tps. 30 and 31 South, Ranges 6 and 7 West. viz.

A post firmly set in the ground, from which

A Laurel, 20 ins. dia., bears N.38*E., 148 lks. dis.
mkd. S 31 T 30 S R 6 W - B T.

A Laurel, 18 ins. dia., bears S.60*E., 20 lks. dis.
Blazes grown over. No marks perceptible.

A Laurel, 2 ins. dia., bears S.51*W., 27 lks. dis.

Old blazes over grown. Scars plain.

A Laurel, 16 ins. dia., bears N.45*W., 200 lks. dis.
mkd. T 30 S R 7 W S 36 B T.