

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R. 6 W.

CHAINS

A Fir, 36 ins. dia., bears S.55*W., 80 lks. dis.
mkd. T 31 S. R 6 W S 35 B T.

A Fir, 30 ins. dia., bears N.15*W., 13 lks. dis.
mkd. T 31 S R 6 W S 26 B T.

Land, mountainous.

Soil; 3rd rate.

Timber, Fir, Pine, Laurel, Cedar and Chinkapin.

Thick undergrowth of Fir, Pine, Laurel, Cedar and Vine
maple.

Va.19*30'E.

East, on a random line bet. secs. 25 and 36.

3.50 Top of ridge, course N. and SE.

40.00 Set temporary $\frac{1}{2}$ sec. cor.

Begin descent through burnt timber.

52.25 Creek, 3 lks. wide, course NE.

Begin steep ascent.

80.78 Intersect East Bdy. of Tp. 60 lks. N. of cor. to secs.
25, 30, 31 and 36, which is a post 3 ins. sq., set
firmly in the ground and marked.

T 31 S R 5 W S 30 on NE.

S 31 on SE.

R 6 W S 36 on SW.

S 25 on NW. face, with 5 notches on N. and 1 notch
on S. edges, from which

A Fir, 20 ins. dia., bears N.38*W., 16 lks. dis.
mkd. T 31 S R 6 W S 25 B T.

A Fir, 36 ins. dia., bears S.33*W., 26 lks. dis.
mkd. T 31 S R 6 W S 36 B T.

A Fir, 20 ins. dia., bears S.68*E., 95 lks. dis.
mkd. T 31 S R 5 W S 31 B T.

A Yew, 14 ins. dia., bears N.31*E., 64 lks. dis.
mkd. T 31 S R 5 W S 30 B T.