

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 31 S., R. 6 W.

CHAINS

Va. 18*15'E.

North, bet. secs. 13 and 14.

Moderate Descent.

29.00 Descend along side hill facing E.

40.00 Set a Fir post, 3 ft. long, 3 ins. sq., 16 ins. in the ground for $\frac{1}{4}$ sec. cor. mkd. $\frac{1}{4}$ S on W. face, from which
 A Fir, 18 ins. dia., bears S.22*E., 12 lks. dis.
 mkd. $\frac{1}{4}$ S B T .
 A Chinkapin, 14 ins. dia., bears N.35*W., 17 lks. dis.
 mkd. $\frac{1}{4}$ S B T.

80.00 A Fir tree, 8 ins. dia., cor. to secs. 11, 12, 13 and 14
 mkd. T 31 S R 6 W S 12 on NE.
 S 13 on SE.
 S 14 on SW. and
 S 11 on NW. faces with 1 notch on E. and 4 notches
 on S. edges, from which,
 A Laurel, 12 ins. dia., bears N.72*E., 65 lks. dis.
 mkd. T 31 S R 6 W S 12 B T.
 A Fir, 10 ins. dia., bears S.45*E., 29 lks. dis.
 mkd. T 31 S R 6 W S 13 B T.
 A Fir, 10 ins. dia., bears S.60*W., 7 lks. dis.
 mkd. T 31 S R 6 W S 14 B T.
 A Laurel, 6 ins. dia., bears N.25*W., 22 lks. dis.
 mkd. T 31 S R 6 W S 11 B T.

Land, mountainous.

Soil, 2nd rate.

Timber, mostly fir with some Pine, Laurel, Cedar and
 Chinkapin.

Thick undergrowth of Fir, Laurel, Chinkapin, Live
 Oak and Balm.