

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R. 6 W.

CHAINS

Land, mountainous.  
 Soil, 3rd rate.  
 Timber, Fir, Pine and Laurel,  
 Thick undergrowth, of Fir, Laurel, Pine, Oak, Hazel  
 and Balm.

July 8, 1882.

Then beginning at the cor. to secs. 3, 4, 33 and 34, on  
 South Bdy. of Tp. which is a post, 4 ins. sq. set firmly  
 in the ground and marked.

T 31 S R 6 W S 34 on NE.

T 32 S S 3 on SE.

S 4 on SW., and

S 33 on NW. faces with 3 notches on E. and W. edges,  
from which,

A Fir, 40 ins. dia., bears N.72\*E., 72 lks. dis.  
mkd. T 31 S R 6 W S 34 B T.

A Fir, 36 ins. dia., bears S.25\*E., 62 lks. dis.  
mkd. T 32 S R.6 W S 3 B T.

A Fir, 30 ins. dia., bears S.4\*W., 76 lks. dis.  
mkd. T 32 S R.6 W S 4 B T.

A Fir, 34 ins. dia., bears N.59\*W., 73 lks. dis.  
mkd. T 31 S R 6 W S 33 B T.

I run North, bet. secs. 33 and 34.

Va.18\*30'E.

Steep descent.

40.00 Set Hemlock post. 3 ft. long, 3 ins. sq., 18 ins. in  
 the ground for the  $\frac{1}{2}$  sec. cor. mkd.  $\frac{1}{4}$  S on the  
 W face, from which,

A Fir, 42 ins. dia., bears N.66\*E., 39 lks. dis.  
mkd.  $\frac{1}{4}$  S B T.