

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31, R. 6 W.

CHAINS

Land, mostly slopes North.

Soil; 2nd rate.

Timber, mostly Fir, with some Pine.

Undergrowth of Fir, Laurel, Balm. and Pine.

East, on random line bet. secs. 28 and 33.

Va. 19*15'E.

- 5.05 Water ditch, course N. Ascend.
- 13.50 Spur, course SW. Descend.
- 21.55 Creek, 2 lks. wide, course SW. Ascend.
- 35.75 Top of spur, course SW.
Sidehill, facing S.
- 40.00 Set tem. $\frac{1}{4}$ sec. cor.
- 53.75 Spring branch, course S. 80*W.
Steep ascent.
- 75.50 Top of spur, course S. Descend.
- 80.72 Intersect N. and S. line 42 lks. N. of cor. to secs.
27, 28, 33 and 34.
Thence I run N. 89*42'W., on true line, bet. secs. 28
and 33, with same Va.
- 40.36 Set a Laurel post, 3 ft. long, 3 ins. sq., 18 ins. in the
ground, for $\frac{1}{4}$ sec. cor. mkd. $\frac{1}{2}$ S. on N. face, from which
A Pine, 34 ins. dia., bears S. 47*W., 73 lks. dis.
mkd. $\frac{1}{4}$ S B T.
A Fir, 30 ins. dia., bears N. 16*W., 109 lks. dis.
mkd. $\frac{1}{4}$ S B T.
- 80.72 The cor. to secs. 28, 29, 32 and 33.
Land, mountainous soil, 3rd rate.
Timber, Fir, Pine, Cedar and Laurel.
Thick undergrowth, of Fir, Pine, Laurel, Cedar and Balm.