

Exteriors of T. 32 S., R. 7 W.,

CHAINS

marked T 31 S R 7 W S 32 on NE face; T 32 S S 5 on SE face; S 6 on SW face; S 31 on NW face, also five notches on E and one on W angles of same from which

A Fir, 15 ins. diam., bears N.10°E., 58 lks. dist.

marked T 31 S R 7 W S 32 B T.

A Laurel, 6 ins. diam., bears S.54°E., 20 lks. dist.

marked T 32 S R 7 W S 5 B T.

A Fir, 36 ins. diam., bears S.32°W., 38 lks. dist.

marked T 32 S R 7 W S 6 B T.

A Laurel, 6 ins. diam., bears N.42°W., 30 lks. dist.

marked T 31 S R 7 W S 31 B T.

Land, mountainous, Soil, clay and loam, 3rd rate.

Timber, chiefly Fir, Pine and Cedar.

Undergrowth, good, dense, of same laurel and vinemaple.

S.89°30'W., on true line bet. secs. 6 and 31.

Va. 17°30'E.

4.70 Creek, 4 lks. wide, C. NW Ascend.

10.50 Top of Spur, C. N. Decent.

17.10 Creek, 80 lks. wide, C. SW.

Ascend along S. Slope of mountain.

40.00 Set a fir post 4 ft. long, 4 ins. sq., 20 ins. in the ground. Marked $\frac{1}{4}$ S. on the N. side for the $\frac{1}{4}$ sec.cor. from which

A Live Oak, 8 ins. diam., bears S.28°E., 10 lks. dist.

A Sugar Pine, 20 ins. diam., bears N.40°W., 11 lks.

Each marked $\frac{1}{4}$ S B T.

75.50 Top of Spur, C. S. Decend.

81.35 To Tp. Cor.

Land, Rolling and broken. Soil, clay and loam, 3rd rate.

Timber, good, chiefly, Fir, Pine, Cedar and Laurel.

Underbrush, Same, live oak and vinemaple.

October 24th, 1881.