

## Subdivisions, T. 31, S., R. 7, W.,

CHAINS	
	North Bet. secs. 25 and 26. Va. 19°E.
6.50	Fence C. E. and W. Ascend along SE slope.
29.80	Creek, 2lks. wide, C. SE.
40.00	Set Laurel post, 3 ft. long, 3 ins. sq., 18 ins. in the ground for $\frac{1}{2}$ sec. cor. marked $\frac{1}{2}$ S. on W. face from which A Live-Oak, 14 ins. diam., bears N.32°W., 85 lks. dist. Marked $\frac{1}{2}$ S B T. A Sugar-Pine, 44 ins. diam., bears S.10°E., 84 lks. Marked $\frac{1}{2}$ S B T.
57.00	Top of Spur, C. SE. Thence along steep sidehill facing E.
72.00	Top of ridge, C. S.20°W., and N.20°E. Thence along W. side of same.
80.00	Set a pine post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, for the cor. to secs. 23, 24, 25 and 26, marked T 31 S R 7 W S 24 on NE; S 25 on SE; S 26 on SW; and S 23 on NW faces, with 1 notch on E. and 2 notches on S. edges from which A Pine, 8 ins. diam., bears N.44°E., 55 lks. dist. Marked T 31 S R 7 W S 24 B T. A Fir, 34 ins. diam., bears S. 40°E., 29 lks. dist. Marked T 31 S R 7 W S 25 B T. A Laurel, 6 ins. diam., bears S.54°W., 22 lks. dist. Marked T 31 S R 7 W S 26 B T A Fir, 12 ins. diam., bears N.70°W., 23 lks. dist. Marked T 31 S R 7 W S 23 B T.
	Land, Mountainous, Soil, 3rd rate. Timber, Pine, Fir, Laurel and Cedar. Thick undergrowth of Fir, Laurel, Pine and Cedar.