

Subdivisions, T 31, S, R.7 W.,

CHAINS	
	North bet. secs. 26 and 27.
	Va. 19°E.
	Descend along steep sidehill facing W.
18.60	Creek, 12 lks. wide, C. S. 15°W.
	Ascend along sidehill, facing E.
40.00	Set pine post, 3 ft. long, 3 ins. sq., 18 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{2}$ S. on W. face from which
	A Pine, 26 ins. diam., bears S.12°W., 28 lks. dist.
	Marked $\frac{1}{4}$ S B T.
	A Pine, 12 ins. diam., bears N.18°E., 62 lks. dist.
	Marked $\frac{1}{4}$ S. B T.
47.60	Creek, 4 lks. wide, C. SE.
	Steep ascent.
78.50	Top of Spur, C. SE.
80.00	Set fir post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for the cor. to secs. 22, 23, 26 and 27, marked
	T 31 S R7 W S 23 on NE; S 26 on SE; S 27 on SW and S 22 on NW faces, with 2 notches on E. and S. edges, from which
	A Fir, 8 ins. diam., bears N.36°E., 21 lks. dist.
	Marked T. 31 S R 7 W S 23 B T.
	A Fir, 12 ins. diam., bears S.48°E., 25 lks. dist.
	Marked T 31 S R 7 W S 26 B T.
	A Fir, 12 ins. diam., bears S.14°W., 29 lks. dist.
	Marked T 31 S R 7 W S 27 B T.
	A Fir, 10 ins. diam., bears N.68°W., 33 lks. dist.
	Marked T 31 S R 7 W S 22 B T.
	Land, mountainous. Soil, 3rd rate.
	Timber, Fir, Pine, Cedar, Laurel.
	Thick undergrowth of Fir, Laurel, Pine and Cedar.