

40

## Subdivisions, T 31 S., R.7 W.,

## CHAINS

- 80.30 To cor. to secs. 21, 22, 27 and 28.  
Land, mountainous and broken. Soil, clay and rocky,  
3rd rate.  
Timbers, chiefly, Fir, Pine, Laurel and Cedar.  
Thick undergrowth of Fir, Laurel, Pine and Cedar.
- 
- North bet. secs. 21 and 22.  
Va. 18°30'E.  
Steep decent.
- 8.45 A creek, 7 lks. wide, C. W. steep ascent.
- 12.50 Steep W. slope of mountain.
- 40.00 Set pine post, 40 ins. long, 4 ins. sq., 18 ins. in the  
ground, marked  $\frac{1}{4}$  S. on W. side for the  $\frac{1}{4}$  sec. cor.  
from which  
A Pine, 36 ins. diam., bears S.50°W., 244 lks. dist.  
Marked  $\frac{1}{4}$  S B T.  
A Pine, 42 ins. diam., bears S.58°E., 206 lks. dist.  
Marked  $\frac{1}{4}$  S B T.
- 55.00 Trail on top of ridge, C. NW and SE. Decend.
- 80.00 Set a cedar post, 4 ft. long, 4 ins. sq., 24 ins. in the  
ground, marked T 31 S R 7 W S 15 on NE face; S 22 on  
SE face; S 21 on the SW face and S16 on NW face, also  
three notches on the S. and E. angles of same for the  
cor. to secs. 15, 16, 21 and 22, from which  
A Fir, 14 ins. diam., bears N.18°E., 49 lks. dist.  
Marked T 31 S R 7 W S 15 B T.  
A Fir, 40 ins. diam., bears S.69°E., 22 lks. dist.  
Marked T 31 S R 7 W B T S 22 B T.  
A Cedar, 24 ins. diam., bears S.58°W., 48 lks. dist.  
Marked T 31 S R 7 W S 21 B T.  
A Fir, 12 ins. diam., bears N.25°W., 9 lks. dist.  
Marked T 31 S R 7 W S 16 B T.