

Subdivisions, T. 31 S., R. 7 W.,

CHAINS

Soil, rocky 4th rate.

Timber, Fir, Pine, Laurel, Cedar and Oak.

Thick undergrowth of Fir, Laurel, Oak, Pine and Cedar.

July 29th, 1882.

From the cor. to secs. 4, 5, 32 and 33 on the S. Bdy. of the Tp. which is a post, 4 ins. sq., marked T 31 S R 7 W S 33 on NE; T 32 S R 7 W S 4 on SE; S 5 on SW and S 32 on the NW; also marked with 4 notches on E. and 2 notches on W. edges from which

A Fir, 14 ins. diam., bears N.54*E., 17 lks. dist.

Marked T 31 S R 7 W S 33 B T.

A Fir, 26 ins. diam., bears S.36*E., 18 lks. dist.

Marked T 32 S R 7 W S 4 B T.

A Fir, 16 ins. diam., bears S.12*W., 60 lks. dist.

Marked T 32 S R 7 W S 5 B T.

A Laurel, 8 ins. diam., bears N.50*W., 9 lks. dist.

Marked T 31 S R 7 W S 32 B T.

Thence I run North bet. secs. 32 and 33.

Va. 18*00'E.

Along W. slope of mountain.

30.00 Steep descent.

40.00 Set a laurel post, 4 ins. sq., 40 ins. long, 20 ins. in the ground, marked $\frac{1}{4}$ S. on W. side for the $\frac{1}{4}$ sec. cor. from which

A Fir, 32 ins. diam., bears N.3*W., 37 lks. dist.

Marked $\frac{1}{4}$ S B T.

A Laurel, 10 ins. diam., bears S.45 lks. dist.

Marked $\frac{1}{4}$ S B T.

64.10 Middle Creek, 80 lks. wide, C. SW. Steep ascent.

71.00 A Creek, 2 lks. wide, C. SE.

80.00 Set a laurel post, 4 ft. long, 4 ins. sq., 22 ins. in the ground marked T 31 S R 7 W S 28 on NE. face; S 33 on SE face, S 32 on SW face and S 29 on NW face, also one