

Subdivisions, T. 31 S. R. 7 W.

CHAINS

Marked T 31 S R 7 W S 20 B T.

A Fir, 26 ins. diam., bears S.24*W., 8 lks. dist.

Marked T 31 S R 7 W S 19 B T.

A Fir, 36 ins. diam., bears N.78*W., 51 lks. dist.

Marked T 31 S R 7 W S 18 B T.

Land, mountainous and broken. Soil, clay and rocky,
3rd rate.

Timber, poor, chiefly, fir, pine, cedar, laurel and
live oak.

Thick undergrowth of fir, laurel, live-oak, pine and
cedar.

East on Random line bet. secs. 17 and 20.

Va. 18*30'E.

3.40 Creek, 10 lks. wide, C. NW.

17.40 Top of rocky point. Thence along

40.00 Set temp. $\frac{1}{4}$ sec. cor.

broken ridges.

80.38 Intersect N. and S. line 14 lks. S. of cor. to secs. 16,
17, 20 and 21. Thence S.89*54'W., on true line bet.
secs. 17 and 20.

40.19 Marked a live-oak, 7 ins. in diam., $\frac{1}{4}$ S. on N. side for
the $\frac{1}{4}$ sec. cor. from which

A Fir, 14 ins. diam., bears S.32*W., 6 lks. dist.

Marked $\frac{1}{4}$ S. B T.

A Live-Oak, 7 ins. diam., bears N.42*E., 16 lks. dist.

Marked $\frac{1}{4}$ S B T.

80.38 To cor. to secs. 17, 18, 19 and 20.

Lands, mountainous and broken. Soil, rocky, 3rd rate.

Timber, Fir, Pine, Cedar, Laurel and Live-Oak.

Thick undergrowth of Fir, Laurel, Pine, Live-Oak and
Cedar.