

South Boundary of T. 31 S., R. 8 W.

CHAINS	
	<p>Land, mountainous.</p> <p>Soil 3d rate.</p> <p>Timber, Fir, pine, laurel, cedar.</p> <p>Thick undergrowth of fir, laurel, pine, and cedar with balm and chincapin.</p>
	<p>West bet. Secs. 5 & 32. Va. 19* East.</p> <p>Ascend.</p>
10.25	Top of Spur, course S. Along S. Slope.
25.00	Steep Descent.
39.50	A Creek, 2 lks. wide, course S.30*W.
40.00	<p>Set stone 14x12x10 ins., 8 ins. in the ground, marked $\frac{1}{4}$ on N. side for the $\frac{1}{4}$ sec. cor., and from which</p> <p style="padding-left: 40px;">A Fir, 52 ins. diam., bears N.9*E., 52 lks. dist.</p> <p style="padding-left: 80px;">Marked $\frac{1}{4}$ S B T</p> <p style="padding-left: 40px;">A Fir, 40 ins. diam., bears S.32*W., 75 lks. dist.</p> <p style="padding-left: 80px;">Marked $\frac{1}{4}$ S B T</p>
	Steep Ascent.
57.00	Top of Spur, course SE. Steep Descent.
75.50	A Creek, 8 lks. wide, course SE.
80.00	<p>Set a stone 16x14x10 ins., 8 ins. in the ground, marked with 5 notches on the E. and 1 notch on the W., for the cor. to Secs. 5, 6, 31 and 32, and from which</p> <p style="padding-left: 40px;">A Live Oak, 5 ins. in diam., bears N.30*E., 44 lks.</p> <p style="padding-left: 80px;">Marked T 31 S R 8 W S 32 B T</p> <p style="padding-left: 40px;">A Fir, 28 ins. diam., bears S.70*E., 42 lks. dist.</p> <p style="padding-left: 80px;">Marked T 32 S R 8 W S 5 B T</p> <p style="padding-left: 40px;">A Fir, 20 ins. diam., bears S.25*W., 56 lks. dist.</p> <p style="padding-left: 80px;">Marked T 32 S R 8 W S 6 B T</p> <p style="padding-left: 40px;">A Fir, 10 ins. diam., bears N.78*W., 38 lks. dist.</p> <p style="padding-left: 80px;">Marked T 31 S R 8 W S 31 B T</p>
	<p>Land, mountainous and broken.</p> <p>Soil, 3d rate.</p> <p>Timber; densely covered with forests of fir, pine, laurel chincapin and cedar.</p> <p>Undergrowth of fir, pine, laurel, chincapin, cedar and</p>