

NORTH BOUNDARY OF T. 32 S. , R. 9 W.,
As surveyed by Richmond S. Dickerson, Deputy Surveyor,
under Contract No. 474, dated May 10 , 1883.

CHAINS

East, on a true line along N. boundary of Sec. 1.
Va. 19*45'E.

Descend, enter green timber.

19.50 A creek 10 lks. wide, course N. steep ascent.

25.00 Along brow of rocky canyon.

30.50 A creek 3 lks. wide, course N.

40.00 Set a stone, 14x12x5 ins. 10 ins. in the ground for
the $\frac{1}{4}$ Sec. cor. from which

A Fir, 18 ins. diam., bears N.45*E., 38 lks.
dist., marked $\frac{1}{4}$ S B T.

A Fir, 16 ins. diam., bears S.45*E., 19 lks.
dist., marked $\frac{1}{4}$ S B T.

45.00 Steep descent.

53.50 West Fork 10 lks. wide, course SE, steep ascent.

60.00 Along S. slope of mountain.

64.40 SW corner to township 31 S R 8 W.

80.00 The corner to township 32 S Ranges 8 and 9 W.

Land, mountainous and broken.

Soil, rocky, 3rd rate, covered with dense forest of
timber, chiefly Fir.

Thick undergrowth of Hazel, Vinemaple, Laurel, Fir
and Balm.

General Description

This township is mountainous, rough and broken with
an occasional glade or bench of good land.

It is generally densely covered with timber (some very
fine) chiefly Fir, Pine, Cedar and Laurel.

There are no settlements to my knowledge in the
township and yet the township should be subdivided.

Richmond S. Dickerson,
U.S. Deputy Surveyor.

June 18th, 1883.