

SOUTH BOUNDARY OF T. 31 S., R. 9 W.

CHAINS

Mountainous, heavily timbered or covered with dense undergrowth. 80.00 chains.

West, on South boundary of Sec. 34.

Ascend in old burn.

16.83 Old $\frac{1}{4}$ Sec. cor. for Sec. 3. Corner and witness trees standing.

26.80 Top of ridge, course N and S. Trail from Camas to Rogue River along summit.

400

Descend.

April 23, 1901.

40.00 Set a Cedar post, 4 ft. long, 4 ins. sq. 24 ins. in ground and marked S 34 $\frac{1}{4}$ S on W. face for the $\frac{1}{4}$ Sec. cor. of Secs. 34, from which:

A Fir, 20 ins. diam., bears S.20*W., 46 lks. dist., marked S 34 $\frac{1}{4}$ S B T.

A Fir, 10 ins. diam., bears N.20*W., 24 lks. dist., marked S 34 $\frac{1}{4}$ S B T.

49.00 A creek 2 lks. wide, course SW.

400

56.74 Old cor. of Secs. 3 and 4. Corner and witness trees standing and agreeing with notes furnished by the Surveyor General,

80.00 Set a Fir post, 4 ins. sq. 4 ft. long, 24 ins. in the ground, for cor. to Secs. 33 and 34, marked S 33 R 9 W on NW, S 34 T 31 S on NE face, with 3 notches on E. and W. edges, from which:

500

A Fir, 30 ins. diam., bears N.8*E., 20 lks. dist., marked T 31 S R 9 W S 34 B T.

A Fir, 24 ins. diam., bears N.20*W., 93 lks. dist., marked T 31 S R 9 W S 33 B T.

Land, mountainous.

Soil, 2nd and 3rd rate.

Timber, Fir, Cedar and Oak.

Undergrowth, heavily timbered or covered with dense undergrowth. 80.00 chains.