

## County Surveyor's Record, Douglas County, Oregon

## RESURVEY OF EAST BOUNDARY OF T. 31 S., R. 9 W.

CHAINS

Corner destroyed. Witness trees standing.

Set a stone, 14x12x8 ins. at the established point for the same, as taken from the witness trees.

Marked the stone with 2 notches on S and 4 notches on N and set 10 ins. in the ground.

Land, mountainous.

Soil, clay and rocky, 3rd rate.

Timber, Fir, Hemlock, Pine, Cedar, Laurel, Chinquapin and Yew.

Undergrowth, same, with Balm, Rhododendron, Vinemaple, Huckleberry and Salal.

Mountainous, heavily timbered or covered with dense undergrowth. 79.92 chains.

From the last named corner I run

North on East boundary of Sec. 24.

3.80 Creek 1 lk. wide, course SW.

Steep ascent.

37.50 Top of spur on line, course S.60\*W.

Enter old burn.

40.08 Point for  $\frac{1}{4}$  Sec. corner.

Post and one witness tree gone.

Set a Fir post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, marked S 19 on E, S 24  $\frac{1}{4}$  S on W faces, for the  $\frac{1}{4}$  Sec. corner from which

A Fir, 18 ins. diam., bears N.71\*E., 72 lks. dist., (old witness tree) marked  $\frac{1}{4}$  S B T.

A Laurel, 6 ins. diam., bears S.30\*W., 9 lks. dist., marked S 24  $\frac{1}{4}$  S B T.

Along W slope of mountain over ridges and canyons.

76.00 Top of spur on line, course SW. Enter green timber.

79.86 The point for Sec. corner.

Post gone - witness trees standing and agree with notes furnished by the Surveyor General.