

RESURVEY OF EAST BOUNDARY OF T. 31 S., R. 9 W.

CHAINS

North, between Secs. 1 and 6.

Ascend SW slope of mountain.

25.50 Top of ridge, course NW and SE.

800

26.50 Descend NE slope of mountain.

40.13 Point for  $\frac{1}{4}$  Sec. corner. Post gone.

Witness trees standing.

Set a Fir post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, marked S 6 on E and S 1  $\frac{1}{2}$  S on W faces, for the  $\frac{1}{4}$  Sec. corner at the point indicated by the witness trees from the field notes furnished by the Surveyor General.

70.36 The corner of Townships 30 and 31 S., Ranges 8 and 9 W.

Corner and witness trees all standing.

Land, mountainous.

Soil, rocky and broken, 4th rate.

Timber, Fir, Hemlock, Cedar, Laurel, Chinquapin and Yew.

Undergrowth, same, with Rhododendron, Balm, Vinemaple, Huckleberry and Salal.

Mountainous, heavily timbered or covered with dense undergrowth. 70.36 chains.

April 29th, 1901.