

West Bdy. of T. 32 S., R. 2 W.

CHAINS

General Description

This township is rough and mountainous in the northern and western part, rolling in eastern and somewhat level in the southern part. In addition to the broken land, there are many high plateaus of rich alluvial land. The region is well watered by the tributaries of Rogue river, Umpqua River and Cow. Creek. The township is heavily timbered in the interior.

Subdivisions of T. 32 S., R. 2 W.,  
Same Deputy and Contract.

N. 0°01'W., between secs. 35 and 36.

80.00

Set a basalt stone, 36x15x4 ins., 20 ins. in ground, mound of stone around for cor. of secs. 25, 26, 35, and 36, marked with 1 notch on S. and E. edges, from which

A fir, 20 ins. diam., bears N.10 $\frac{1}{2}$ \*E., 68 lks. dist.

Marked T 32 S R 2 W S 25 B T.

A fir, 38 ins. diam., bears S.11\*E., 68 lks. dist.

Marked T 32 S R 2 W S 35 B T.

A fir, 20 ins. diam., bears N.28 $\frac{1}{2}$ \*W., 73 lks. dist.

Marked T 32 S R 2 W S 26 B.T.

Land, rolling and mountainous.

Soil, sandy and stoney, third and fourth rate.

Timber, fir, yello pine and sugar pine.

Undergrowth, laurel, small firs, buck brush .

Mountainous and densely covered with undergrowthlands.

East, on a random line between secs. 25 and 36.

40.00

Set temp.  $\frac{1}{4}$  sec. cor.

80.14

Intersect E. Bdy. of Tp. 14 lks. S. of the cor. of secs. 25, 30, 31 and 36, which is a basalt stone, 6x8x6 ins. above ground, marked and witnesses as described by the surveyor general.

Thence, I run S.89\*54'W. on a true line between secs. 25 and 36.