

County Surveyor's Record, Douglas County, Oregon

Dependent resurvey of E. Bdy. of T. 32 S., R. 3 W.

CHAINS

- 52.50 Creek, 6 lks. wide, course NW., ascend S. slope.
- 69.75 Spur, slopes W., along W. slope.
- 91.10 Intersect the cor. of secs. 18 and 19, T. 32 S., R. 2 W., which is a stone, firmly set, marked and witnessed as described by the Surveyor General. As no bearing tree was formerly taken in sec. 18, I re-witness this cor. as follows: From the cor. already set
- A madrona, 20 ins. diam., bears N.46°E., 131 lks.
Marked T 32 S R 2 W S 18 B T.
- A fir, 48 ins. diam., bears S.8°E., 45 lks. dist.
Marked T 32 S R 2 W S 19 B T.
- I continue my measurements
North on true line along E. bdy. of sec. 24.
- 97.77 Intersect the closing cor. of secs. 13 and 24, which is a stone, firmly set, marked and witnessed as described by the Surveyor General.
- Land, mountainous.
- Soil, decomposed granite, third rate.
- Timber, fir, hemlock and madrona.
- Undergrowth, madrona, lilac and snowbrush.