

Subdivisions of T. 32 S., R. 3 W.

CHAINS	West on a true line, between Secs. 11 and 14.	
40.00	Set $\frac{1}{2}$ Sec. post, no trees standing. Builded up a stone mound about post.	
50.00	Top of ridge, course North and South.	+200
80.00	The cor. to Secs. 10, 11, 14 and 15. Land, mountainous, third rate. Timber, poor, third rate. Underbrush, very thick. Manzanita and Laurel. September 22, 1871.	-1250
	South, between Secs. 14 and 15. Va. 20° E.	
4.50	A creek, 2 lks. wide, course West.	-150
17.50	Top of spur, course West.	+400
40.00	Set $\frac{1}{4}$ Sec. post, from which A Fir, 30 ins. diam., bears N. 60° E., 28 lks. dist. A Fir, 8 ins. diam., bears S. 70° W., 22 lks. dist.	-50
40.50	A creek, 3 lks. wide, course West.	-50
70.00	Top of timbered ridge, course West and East.	+1000
80.00	Set post, cor. to Secs. 14, 15, 22 and 23, from which A Fir, 8 ins. diam., bears N. 70° E., 25 lks. dist. A Fir, 8 ins. diam., bears S. 30° E., 34 lks. dist. A Fir, 10 ins. diam., bears S. 15° W., 22 lks. dist. A Fir, 30 ins. diam., bears N. 70° W., 15 lks. dist. Land, hilly; second rate. Timber, Fir, Pine, Cedar, Hemlock, Maple and Yew. Underbrush, same and mountain Laurel.	+700
	South, between Secs. 3 and 4. Va. 20° E.	
10.00	Down a dry ravine. Timber burned.	-50
30.00	Leave ravine.	
35.00	Enter green timber.	-200