

East Bdy. of Tp. 32 S., R. 4 W.

CHAINS	
	A Fir, 50 ins. diam., bears West, 18 lks. dist., marked $\frac{1}{4}$ S B T.
	This cor. is on a hillside, sloping SE. about 50 ft. below spur.
44.00	Creek, 1 lk. wide, course East, 50 ft. below $\frac{1}{4}$ Sec. cor.; ascend.
45.75	Spur, sloping East, 25 ft. above last creek; descend.
48.00	Creek, 1 lk. wide, course East 25 ft. below top of last spur; ascend.
62.00	Top of spur, sloping East 25 ft. above last creek; descend.
74.10	Creek, 1 lk. wide, course East 50 ft. below top of last spur; ascend.
78.50	Top of spur, sloping East, 15 ft. above creek; descend.
80.00	Set a basalt stone 14 x 12 x 6 ins., 9 ins. in the ground. for cor. of Secs. 18, 19, 24 and 13, marked with 3 notches on North and South edges, from which A Chinquapin, 7 ins. diam., bears N.88*E., 24 lks. dist., marked T 32 S R 3 W S 18 B T. A Madrona, 8 ins. diam., bears S.39*E., 19 lks. dist., marked T 32 S R 3 W S 19 B T. A Cedar, 50 ins. diam., bears S.40*W., 11 lks. dist., marked T 32 S R 4 W S 24 B T. A Fir, 24 ins. diam., bears N.57*W., 23 lks. dist., marked T 32 S R 4 W S 13 B T.
	This cor. is on hillside sloping South 25 ft. below top of last spur.
	Land, mountainous.
	Soil, third rate.
	Timber, Fir, Cedar, Hemlock, Madrona, Maple, Chinquapin, Alder and Yew.
	Dense undergrowth of rhododendron, Chinquapin, Hazel,