

East Bdy. of T. 32 S., R. 4 W.

CHAINS

Soil, 4th rate, rocky.

Timber, Fir, Pine, Cedar, Hemlock, Chinquapin, Maple and Madrona.

Dense undergrowth of Rhodendron, Mountain Balm, Manzanita and Vine Maple.

Land, mountainous, heavily timbered or covered with dense undergrowth, 80.00 chs.

South, on true line, between Secs. 31 and 36.

Descend.

- 1.75 Creek, 4 lks. wide, course S.70°E., 50 ft. below Sec. cor.; ascend spur.
- 16.25 Spur, sloping East 150 ft. above creek; descend into canyon.
- 27.25 Bottom of canyon, 150 ft. below last spur, bears East and West; ascend spur.
- 34.25 Top of spur, sloping East 150 ft. above canyon; descend.
- 38.25 Ravine, sloping East 50 ft. below top of spur; thence, along hillside sloping East.
- 40.00 Set a basalt stone 16 x 14 x 8 ins., 11 ins. in the ground, for $\frac{1}{4}$ Sec. cor., marked $\frac{1}{4}$ on West face, from which
 - A Fir, 12 ins. diam., bears S.51 $\frac{1}{2}$ *E., 236 lks. dist., marked $\frac{1}{4}$ S B T.
 - A Fir, 12 ins. diam., bears N.76 $\frac{1}{2}$ *W., 53 lks. dist., marked $\frac{1}{4}$ S B T.

This $\frac{1}{4}$ Sec. cor. is on a steep hillside, sloping East.
- 48.75 Spur, sloping SE.
Begin descent.
- 99.35 Intersect 7th Standard Parallel South, 22.89 chs. West of the standard cor. of Tp. 32 S., R's. 3 and 4 W., which is a Cedar post, 24 ins. above ground, marked and wit-